



2015 SPANISH GRAND PRIX

| | | | |
|-------------|--|-----------------|-------------|
| From | The FIA Formula One Technical Delegate | Document | 17 |
| To | The FIA Stewards of the Meeting | Date | 08 May 2015 |
| | | Time | 20:15 |

The following drivers will start the fifth Event of the 2015 Formula One World Championship with a new gearbox:

| <i>Number</i> | <i>Car</i> | <i>Driver</i> |
|----------------------|-------------------|----------------------|
| 55 | STR Renault | Carlos Sainz |

The above driver did not finish the last race in Shakir and is in conformity with Article 28.6a of the 2015 Formula One Sporting Regulations.

| <i>Number</i> | <i>Car</i> | <i>Driver</i> |
|----------------------|-------------------|----------------------|
| 22 | McLaren Honda | Jenson Button |

The above driver did not start the last race in Shakir and is in conformity with Article 28.6a of the 2015 Formula One Sporting Regulations.

A seal was broken on the gearbox of car number 08, driver Romain Grosjean, in order to change the hydraulic differential actuator.

This was done in accordance with Article 9.5.2 of the 2015 FIA Formula One Technical Regulations.

Jo Bauer

The FIA Formula One Technical Delegate