



2015 AUSTRIAN GRAND PRIX

From	The FIA Stewards of the Meeting	Document	11
To	The Team Manager, Infiniti Red Bull Racing	Date	19 June 2015
		Time	11:59

The Stewards, having received a report from the Technical Delegate (document 8), and having considered the following matter, determine a breach of the regulations has been committed by the competitor named below and impose the penalty referred to.

No / Driver 3 - Daniel Ricciardo

Competitor Infiniti Red Bull Racing

Time 10:03

Session Practice 1

Fact A 5th internal combustion engine has been used.

Offence Breach of Article 28.4 (a) of the FIA Formula One Sporting Regulations.

Decision Drop of 10 grid positions.

Reason A 5th ICE has been used by car 3, this is a breach of Article 28.4 a) of the FIA Formula One Sporting Regulations. In accordance with Article 28.4 c) a 10 grid position penalty is imposed, as this is the first time a 5th power unit element has been used.

The team notified the Technical Delegate of the change of the ICE on Monday 15th June, at 14:43.

Paul Gutjahr

Radovan Novak

Danny Sullivan

Walter Jobst

The FIA Stewards of the Meeting