



2016 MALAYSIAN GRAND PRIX

From	The FIA Stewards of the Meeting	Document	19
To	The Team Manager, McLaren Honda	Date	01 October 2016
		Time	16:41

The Stewards, having received a report from the Technical Delegate (document 16), have considered the following matter, determine a breach of the regulations has been committed by the competitor named below and impose the penalty referred to.

No / Driver 14 - Fernando Alonso

Competitor McLaren Honda

Time 14:00

Session Practice 3

Fact A 9th Turbo Charger and 9th MGU-H have been used.

Offence Breach of Article 23.4 (a) of the FIA Formula One Sporting Regulations.

Decision Drop of 15 grid positions, comprising :
1) 10 grid positions for 9th TC (1st 9th element used)
2) 5 grid positions for 9th MGU-H (remaining element used)

Reason A 15 grid position penalty is imposed as detailed above in accordance with Articles 23.4 a) and 23.4 f).

The team notified the Technical Delegate regarding the change of the power unit elements on the 26th September, at 23:39.

Tim Mayer

Steve Chopping

Derek Warwick

James Leong Weng Hoong

The FIA Stewards of the Meeting