



## 2016 CANADIAN GRAND PRIX

---

<b>From</b>	The FIA Formula One Technical Delegate	<b>Document</b>	4
<b>To</b>	The FIA Stewards of the Meeting	<b>Date</b>	09 June 2016
		<b>Time</b>	14:27

---

### Technical Delegate's Report

Between 10:00 and 14:05 today the following cars underwent initial scrutineering:

<b>Car numbers</b>	<b>Team</b>
44, 6	: Mercedes AMG Petronas Formula One Team
5, 7	: Scuderia Ferrari
19, 77	: Williams Martini Racing
3, 33	: Red Bull Racing
27, 11	: Sahara Force India F1 Team
20, 30	: Renault Sport Formula 1 Team
26, 55	: Scuderia Toro Rosso
9, 12	: Sauber F1 Team
14, 22	: McLaren Honda Formula 1 Team
94, 88	: Manor Racing MRT
8, 21	: Haas F1 Team

All the above cars were found to be in conformity with the safety requirements of the 2016 FIA Formula One Technical Regulations.

A seal was broken on the gearbox of car number 09, driver Marcus Ericsson, in order to inspect the gear ratios and associated dog rings for physical damage and as a consequence of this inspection to change the 1st and 2nd change gear ratio pair. This was done in accordance with Article 23.6d of the 2016 Formula One Sporting Regulations.

**Jo Bauer**

**The FIA Formula One Technical Delegate**