



2021 ZANDVOORT EVENT

2 to 5 September 2021

From	The FIA Formula 3 Technical Delegate	Document	10
To	The Stewards	Date	03 September 2021
		Time	16:40

Title F3 Technical Delegates Report 2
Description F3 Technical Delegates Report 2
Enclosed 2021_06_Technical_Report_02.pdf

Jana Muhlnr

The FIA Formula 3 Technical Delegate



ZANDVOORT EVENT

2ND – 5TH SEPTEMBER 2021

From	The FIA Formula 3 Technical Delegate	Document	10
To	The Stewards	Date	03.09.2021
		Time	16:40

Technical Delegate's Report

During the free practice session:

All cars had their tyre codes recorded.

The following cars were weighed

<u>No.</u>	<u>Driver</u>	<u>Team</u>
4	Jack Doohan	Trident
5	Clement Novalak	Trident
11	Ayumu Iwasa	Hitech Grand Prix

After the free practice session:

The car 3, 6, 8, 11, 15 and 25 were checked for the correct skid plank nomination.

During the qualifying session:

All cars had their tyre codes recorded and were checked for the correct allocation.

The following cars were weighed

<u>No.</u>	<u>Driver</u>	<u>Team</u>
8	Alexander Smolyar	ART Grand Prix
9	Juan Manuel Correa	ART Grand Prix
14	Matteo Nannini	HWA RACELAB
15	Oliver Rasmussen	HWA RACELAB
20	Laszlo Toth	Campos Racing
25	Jonny Edgar	Carlin Buzz Racing
28	Filip Ugran	Jenzer Motorsport
29	Logan Sargeant	Charouz Racing System



ZANDVOORT EVENT

2ND – 5TH SEPTEMBER 2021

After the qualifying session:

The following cars were weighed

<u>No.</u>	<u>Driver</u>	<u>Team</u>
1	Dennis Hauger	PREMA Racing
4	Jack Doohan	Trident
6	David Schumacher	Trident
8	Alexander Smolyar	ART Grand Prix
10	Jak Crawford	Hitech Grand Prix
17	Victor Martins	MP Motorsport
22	Amaury Cordeel	Campos Racing

All the above cars were checked for:

- 1) Front and rear wing width and height.
- 2) Under floor height.
- 3) Rear diffuser height.
- 4) Wheel camber conformity.
- 5) Rear wing gurney conformity.

The skid planks were checked for thickness and nomination on car numbers **1, 6, 17** and **22**.

The clutch and the drive shaft were checked for conformity on car numbers **1, 6** and **17**.

The engine ECU was checked for conformity on car numbers **1, 4, 6, 8, 10, 17** and **22**.

The gearbox gear ratios were checked for conformity on car numbers **1, 4, 6, 8, 10, 17** and **22**.

The tyre pressures were checked for conformity on car numbers **1, 4, 6, 8, 10, 17** and **22**.

All cars had their tyre codes recorded and were checked for the correct allocation.

All driver weights have been recorded.

All the above items and car weights were found to be in conformity with the requirements of the 2021 Formula 3 Championship Regulations.

Jana Mühlner
FIA F3 Technical Delegate